



Skydive Spain Rigging Facility 2010

SERVICE	PRICE	Comment
Reserve & Harness Inspection and Repack	55 €	
Tandem reserve repack	85 €	
Main inspection & repack	5 €	
Tandem main inspection & packing	10 €	
Assemble new equipment	20 €	
Various rigging work	50 €	per hour
BOC pocket & fitting	55 €	
Pilot chutes	60 €	+fitting
Freely Pud	15 €	
Collapsible kill lin bridle	60 €	
Kill line replacement	20 €	
Normal bridle line	30 €	
Deployment bag	70 €	
Slider	55 €	
Replace slider drawstring channels x 2	40 €	
Collapsible slider	90 €	
Standard control toggels (Pair)	30 €	
Risers	150 €	
Cutaway pad	35 €	
Reserve handle	55 €	
Slider bumper	2 €	
Elastic keeper	2 €	
Closing loop	2 €	
Standart patch in canopy	25 €	
Canopy patch into unloaded seam	35 €	
Canopy patch into loaded seam or tail	40 €	
Lower control line replacement x 2	20 €	
LCL replacement for Katana, Velocity Or other 2 piece control set	35 €	
Middle control line replacement	25 €	
Line replacement per line	30 €	
New line set fitting	100 €	plus lines

Notes:

If any item that has to be custom ordered then the postage, insurance and customs will be charged as an extra and the current exchange rate will apply. 5% will be charged for all credit card payments in the office.